

PROGRESS OF WORKS ON SITE (1 of 2)

Piling works



Pile Caps at Area 100 and 110



Pile Caps casting at Area 100



Dredging for sand dam in progress



Area 100 - Fixing pile cap reinforcement - completed



Area 100 - casting driven piles



PROGRESS OF WORKS ON SITE (2 of 2)

